

S.No.	Description
	<b>SURVEY LAB</b>
<b>01.</b>	<b>CHAINS</b>
	a) CHAIN (30m,150links)
	b) CHAIN (20m,100links)
	c) REVENUE CHAIN
	d) ENGINEER'S CHAIN
	e) STEEL BAND CHAIN
	f) GUNTER'S CHAIN
<b>02.</b>	<b>TAPES</b>
	a) METALLIC TAPES
	b) PLASTIC TAPES
	c) STEEL TAPES- 30m
	d) INVAR TAPE
<b>03.</b>	<b>ARROWS</b>
<b>04.</b>	<b>RANGING RODS</b>
	a) RANGING RODS(2M) (AS ONE-PIECE)
	b) RANGING RODS(3M) (AS ONE-PIECE)
<b>05.</b>	<b>CROSS STAFF</b>
	a) WOODEN CROSS STAFF
	b) OPEN CROSS STAFF
	c) FRENCH CROSS STAFF
<b>06.</b>	<b>PLUMBOB</b>
<b>07.</b>	<b>PEGS</b>
	a) WOODEN PEGS
	b) IRON PEGS
<b>08.</b>	<b>WOODEN MALLET</b>
<b>09.</b>	<b>HAMMER</b>
<b>10.</b>	<b>OPTICAL SQUARE</b>
<b>11.</b>	<b>PRISM SQUARE</b>
<b>12.</b>	<b>LINE RANGER</b>
<b>13.</b>	<b>ABNEY LEVEL</b>
<b>14.</b>	<b>INDIAN PATTERN CLINOMETER</b>
<b>15.</b>	<b>PENTAGRAPH BRASS</b>
<b>16.</b>	<b>DIGITAL PLANIMETER</b>
<b>17.</b>	<b>PRISMATIC COMPASS</b>
<b>18.</b>	<b>SURVEYOR'S COMPASS</b>
<b>19.</b>	<b>DUMPY LEVEL</b>

20.	<b>AUTOMATIC LEVEL</b>
21.	<b>WYE LEVEL</b>
22.	<b>REVERSIBLE LEVEL</b>
23.	<b>LEVELLING STAVES</b>
	a) <b>TELESCOPIC STAFF</b>
	b) <b>FOLDING STAFF</b>
	c) <b>SOLID STAFF</b>
	d) <b>TARGET STAFF</b>
24.	<b>TRANSIT VERNIER THEODOLITE</b>
25.	<b>ELECTRONIC DIGITAL THEODOLITE</b>
26.	<b>ELECTRONIC TOTAL STATION</b>
27.	<b>EDM (Electronic Distance Measurement)</b>
28.	<b>GLOBAL POSITIONING SYSTEM, HAND HELD</b>